



WATER TEMPERATURE SENSOR WATER TEMPERATURE SENSOR INSPECTION

INSPECT WATER TEMPERATURE SENSOR

Using an ohmmeter, measure the resistance of the water temperature sensor.

Water temperature	Resistance
85°C (185°F)	approx. 1.35 kΩ
90° C (194° F)	approx. 1.19 kΩ
95° C (203° F)	approx. 1.05 kΩ

If resistance value is not as specified, replace the sensor.